



## Change List for Win8 Driver 10.0.0.67 to 10.0.0.221

Update 12/01/2012

Qualcomm Atheros is continuing Hot Fixes. This will be a list of running changes as we continue to fix defects against Win8 10.0.0.x base code.

### Software changes between build 10.0.0.67 and 10.0.0.75 (Win8 SID: 1510118)

- 1) Add concurrency mode support for BT coex
- 2) OCS throughput tuning
- 3) Fixed BSOD issue
- 4) Update INF entries

### Software changes between build 10.0.0.75 and 10.0.0.200 (Win8 SID: 1515414)

- 5) Fix the issue about WLAN status is incorrect in the PC Setting
- 6) Fix the ping lost issue on WB222
- 7) Fix the BSOD (athrx!ath\_bt\_watchdog\_timer)
- 8) Add manual peak detector support for Jupiter and Aphrodite
- 9) Fix the BSOD occurred by athrx.sys when DUT reconnect to AP after changes security key
- 10) Update INF entries

### Software changes between build 10.0.0.200 and 10.0.0.209 (Win8 SID: 1523213)

- 11) Fixed the power management issue in "Medium Power Saving" mode.
- 12) Fixed issue of "timers expirations" when running Microsoft ADK tool.
- 13) Fixed scan issue of hidden SSIDs.
- 14) Fixed issue of BT AMP link establishment in some regulatory environments.
- 15) Update INF entries.
- 16) Fixed issue that scan got cancelled due to immediately following OID requests from OS.
- 17) Fixed BSOD 0x133.
- 18) Fixed issue of AR9485 yellow mark on AMD platform when just resuming from S3.
- 19) Fixed BSOD 0xD1.

### Software changes between build 10.0.0.209 and 10.0.0.216 (Win8 SID: 1531021)

- 20) Modify the scan mechanism to improve the connectivity
- 21) Add WPP trace in the driver
- 22) Fix the P2P related issue
- 23) Fix the BSOD occurred by the stress test
- 24) Update INF entries

### Software changes between build 10.0.0.216 and 10.0.0.221 (Win8 SID: 1546672)

- 25) Fixed the issue of the abnormal power consumption.
- 26) Fixed the issue of the "Red-X" after a while in un-associated idle state.



## **Change List for Win8 Driver 10.0.0.67 to 10.0.0.221**

Update 12/01/2012

- 27) Fix the issue of the WLAN disconnects AP for 1 min when it associates AP for several hours.
- 28) Fixed the issue of Wifi display connection will disconnect unexceptly when do long time video playing.
- 29) Fixed BSOD 0x133 and 0x7E
- 30) Update INF entries
- 31) Address AR9485 Yellow Bang/lost