

Intel® PROSet/Wireless for Bluetooth Technology Software 2.6.1211 PV

PV version – 2.6.1211

PCCG Wireless Marketing

WW50 ` 2012



Legal Disclaimer

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL® PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. INTEL PRODUCTS ARE NOT INTENDED FOR USE IN MEDICAL, LIFE SAVING, OR LIFE SUSTAINING APPLICATIONS.

Intel may make changes to specifications and product descriptions at any time, without notice.

All products, dates, and figures specified are preliminary based on current expectations, and subject to change w/o notice.

Intel, processors, chipsets, and desktop boards may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Any code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion or marketing of any product or services and any such use of Intel's internal code names is at the sole risk of the user.

Intel product plans in this presentation do not constitute Intel plan of record product roadmaps. Please contact your Intel representative to obtain Intel's current plan of record product roadmaps.

Software and workloads used in performance tests may have been optimized for performance only on Intel microprocessors. Performance tests, such as SYSmark and MobileMark, are measured using specific computer systems, components, software, operations and functions. Any change to any of those factors may cause the results to vary. You should consult other information and performance tests to assist you in fully evaluating your contemplated purchases, including the performance of that product when combined with other products. For more information go to <http://www.intel.com/performance>

Intel, Intel Inside, the Intel logo, Centrino, Centrino Inside, Intel Core, Intel Atom and Pentium are trademarks of Intel Corporation in the United States and other countries.

Material in this presentation is intended as product positioning and *not* approved end user messaging.

This document contains information on products in the design phase of development.

*Other names and brands may be claimed as the property of others.

Copyright © 2012 Intel Corporation, All Rights Reserved

Legal Disclaimer

Intel® Smart Connect Technology requires a select Intel® processor, Intel® software and BIOS update, Intel® Wireless adaptor, and Internet connectivity. Solid state memory or drive equivalent may be required. Depending on system configuration, your results may vary. Contact your system manufacturer for more information.

Intel® Wireless Display (Intel® WiDi) requires an Intel® Wireless Display enabled PC, compatible adapter, and TV. 1080p and Blu-Ray* or other protected content playback only available on 2nd generation Intel® Core™ processor-based PCs with built-in visuals enabled. Consult your PC manufacturer. For more information, see www.intel.com/go/wid.

Intel® vPro™ Technology is sophisticated and requires setup and activation. Availability of features and results will depend upon the setup and configuration of your hardware, software and IT environment. To learn more visit: <http://www.intel.com/technology/vpro>.

Security features enabled by Intel® AMT require an enabled chipset, network hardware and software and a corporate network connection. Intel AMT may not be available or certain capabilities may be limited over a host OS-based VPN or when connecting wirelessly, on battery power, sleeping, hibernating or powered off. Setup requires configuration and may require scripting with the management console or further integration into existing security frameworks, and modifications or implementation of new business processes. For more information, see <http://www.intel.com/technology/manage/iamt>.

WiMAX connectivity requires a WiMAX enabled device and subscription to a WiMAX broadband service. WiMAX connectivity may require you to purchase additional software or hardware at extra cost. Availability of WiMAX is limited, check with your service provider for details on availability and network limitations. Broadband performance and results may vary due to environment factors and other variables. See www.intel.com/go/wimax for more information.

Intel® My WiFi Technology (Intel® MWT) is an optional feature and requires additional software and an Intel® Centrino® wireless adapter. Wi-Fi devices must be certified by the WiFi Alliance for 802.11a/g/n and Wi-Fi Direct* in order to connect. See www.intel.com/network/connectivity/products/wireless/mywifi.htm for more details.

No system can provide absolute security under all conditions. Requires an enabled chipset, BIOS, firmware and software and a subscription with a capable Service Provider. Consult your system manufacturer and Service Provider for availability and functionality. Intel assumes no liability for lost or stolen data and/or systems or any other damages resulting thereof. For more information, visit <http://www.intel.com/go/anti-theft>.

(Built-in Visuals) Available on the 2nd gen Intel® Core™ processor family. Includes Intel® HD Graphics, Intel® Quick Sync Video, Intel® Clear Video HD Technology, Intel® InTru™ 3D Technology, and Intel® Advanced Vector Extensions. Also optionally includes Intel® Wireless Display depending on whether enabled on a given system or not. Whether you will receive the benefits of built-in visuals depends upon the particular design of the PC you choose. Consult your PC manufacturer whether built-in visuals are enabled on your system. Learn more about built-in visuals at <http://www.intel.com/technology/visualtechnology/index.htm>.

Intel® Insider™ is a hardware-based content protection mechanism. Requires a 2nd generation Intel® Core™ processor-based PC with built-in visuals enabled, an Internet connection, and content purchase or rental from qualified providers. Consult your PC manufacturer. For more information, visit www.intel.com/go/intelinsider.

General Information

- Intel® announces the release of version 1211 for Bluetooth.
- The product version on this release is v2.6.1211
- VIP Kit Number:
 - Kit: 50328
 - TIC THBTW0304G
- Supported OS:
 - This release will support the following OS
 - XP*
 - Vista*
 - Win 7 (32/64)
 - Windows 8 (32/64)

* Code frozen for future releases

Key Features and Supported HW

- Support for all OS
- Improve Tug Hill 2.6.1210 SW quality
- The 2.6.1211 release will update over the 2.6.1210 in addition to previous 2.5 version
 - Note: A reboot is required in all cases, including software uninstall
- **Supported HW:**
 - Intel® Centrino® Wireless-N 1030
 - Intel® Centrino® Advanced-N 6230
 - Intel® Centrino® Wireless-N 2230
 - Intel® Centrino® Advanced-N 6235
 - Intel® Centrino® Wireless-N 130
 - Intel® Centrino® Wireless-N 135

Fixed Issues

ID	Title
MWG100150462	BT Icon disappears from SyTray after S5 cycles (warm) during FTP
MWG100151294	Documentation for customers that BT SW RF Kill (via GUI custom install) and BT driver disable_enable is recommended to not be used simultaneously
MWG100156520	AVRCP "Stop" button is greyed out 3 rd party until WMP is opened on DUT
MWG100156923	FTP get from 3 rd party, progress bar does not show any progress, files > 2GB.
MWG100161532	When running the 2.2 Beta installer, the window opens up in the background and does not display an icon on the task bar
MWG100161731	BLE HID device icons and device properties are incorrect
MWG100162665	BT Uninstall Hangs After Repairing
MWG100164345	Shows Unknown in PC setting device
MWG100164465	Pairing/unpairing a device, then cycling HW RF Kill, results in BSOD
MWG100164985	With no NIC Install will not complete BT Device Monitor fails to start
MWG100165530	If AVRCP controls are open on screen when remote disconnects from A2DP/AVRCP, the user is still able to control the BTOE

Fixed Issues

ID	Title
MWG100166301	Battery level fly out window pop up in wrong position when click on battery level systray icon
MWG100169390	After entering S3/S4 during OPP receive, the next file you receive after resuming does not prompt you to accept
MWG100169450	Windows explorer resets after FTP Get.
MWG100169598	Error message appears when shutting down computer during FTP GET
MWG100169750	Install: Never any BT HW on the system, BT installer cannot uninstall
MWG100163538	Win8 BT headset music jittering while connected to BT mouse and transferring file
MWG100162366	Cannot discover more than 5 characteristic descriptors via GATT
MWG100166245	Power off BLE keyboard, battery level systra...
MWG100168285	Unable to browse remote folder of HTC Vivid or HTC..
MWG100171687	Overlay install package showing incorrect publisher

Limitations

Limitation	Details
SW RF Kill	Does not disable the BT driver during BLE paging.
SW RF Kill	Connection termination does not happen when BT SW RF kill enabled including BT driver disable
SW RF Kill	"Could not turn off" (red) devices in Airplane mode, Win 8 , PC Settings, Wireless
HW RF Kill	BT Icon Does Not Re-Appear on Task Bar After Enable SW+HW RF Kill -> S5Warm/Cold -> Disable SW+HW RF Kill
Translations	UI translation quality is poor and inconsistent

Bluetooth Logging:

Please use this trace kit to capture ETL logs:

<https://backup.filesanywhere.com/fs/v.aspx?v=8c6b67875f5f6db3a56a>

Logging Scripts Definitions:

File	Description
pe-boot-trace-common- <code>{action}</code> .cmd	Collects logs from the boot time. Shall be used for any problem that requires log collection during boot time.
pe-trace-common- <code>{action}</code> .cmd	Collects logs for problems that cannot be explicitly placed to any category from below.
pe-trace-lehid- <code>{action}</code> .cmd	Collects logs for LE HID related problems.
pe-trace-media- <code>{action}</code> .cmd	Collects logs for Media profiles related problems
pe-trace-obex- <code>{action}</code> .cmd	Collects logs for OBEX profiles related problems
pe-trace-skype- <code>{action}</code> .cmd	Collects logs for Skype related problems

Note: `{action}` may be 'start' or 'stop'



Bluetooth Logging Continued:

Process to capture ETL logs:

1. Unzip trace kit package provided with the release.
2. Identify problem area (see previous slide) and select appropriate start script to run.

Example: Let's assume that it is needed to collect log for OBEX-related problem. So in this case, `pe-trace-obex-{action}.cmd` set shall be used.

3. Run `pe-trace-obex-start.cmd` with administrator privileges to start the tracing: right mouse click on `pe-trace-obex-start.cmd` and "run as administrator".
4. Perform the steps to reproduce the problem you want to report.
5. Run `pe-trace-obex-stop.cmd` to with administrator privileges to stop the tracing: right mouse click on `pe-trace-obex-stop.cmd` and "run as administrator".
6. After step 5 `log_*.etl` files should appear in the current directory.
7. Deliver `log_*.etl` logs to Intel rep.

