SW Re-flash Guide

Model Supported: ASUS VivoTab^{TM} RT

Version:1.0

Prepared for:

☐ ASUS Internal Release
☑ Customer

Prepared by: TF600TG PM Team

Service Team

Engineering Team

1. SW Image Re-flash

1.1. Ensure the Device is in Proper State for SW Image Re-flash

Step 1: Ensure the device has at least 50% battery

Step 2: Plug the USB Dongle (or Keyboard dock) into the device

1.2. Update Modem Firmware

**Step 1:** Plug the USB Dongle (or Keyboard dock) into the device

Step 2: Plug the Tools USB thumb drive into USB Dongle (or Keyboard dock)

**Step 3:** Press "Desktop" tile in Start Menu

**Step 4:** Press "File Explorer" in bottom left corner

**Step 5:** Press on "Computer" on the left side

Step 6: Long press (or right click if using Keyboard Dock) on "Computer" to and then press "Manage"


Step 7: The Computer Management window will pop out, press "Device Manager" on the left side, and then press "View" in the Menu bar


**Step 8:** Press "Show hidden devices" under View

Step 9.1: Expand the "Software devices" in the middle, and long press (or right click if using Keyboard Dock) on "Mobile Broadband Firmware Device". Go to step 10.1.


Step 9.2: Expand the "Firmware" if you **cannot** find "Mobile Broadband Firmware Device" in step 9.1 and long press (or right click if using Keyboard Dock) on "ASUS TF600TG Firmware Update Device". Go to step 10.2.

**Step 10.1:** Press "Update Driver Software…" Go to step 11.

**Step 10.2:** Press "Update Driver Software…"

**Step 11:** Press "Browse my computer for driver software"

**Step 12:** Press "Browse" so select the folder modem file is in

Step 13: Navigate to the USB thumb drive and select the folder "__1.2 Update Modem FW", and then press "OK"

Step 14: Verify the path to search in is "<<USB thumb drive>>:__1.2 Update Modem FW", and then press "Next"

Step 15: The modem FW will automatically update and show the following screen upon success

1.3. Verify SW Image

Step 1: Double click folder " __1.3 Verify SW Image"

Step 2: Click on "File" in the top left corner of the window

Step 3: Long press on the 'MODEMCHECK.bat' and select "Run as administrator"

Step 4: Press "Yes" when Command Prompt's UAC prompt pops up

Step 5: The script will automatically check to see if all parts of SW flashing process has been complete as intended. Upon success, you will see the following screen.