


SOP for Firmware Re-flashing



TSST Korea.
Rev 1.0



CONTENTS

1 Material

2 SOP

3 Caution



MATERIAL



One Click Tool(TS-L632H_AS04)

■ Check ODD Model (by hardware)




- a. Check model name on ODD label
→ It should be “TS-L632H”

Check model name on ODD label


■ Check ODD Model (by software)



- a. Run “My Computer”
- b. Click mouse right button
- c. Select “Properties”



■ Check ODD Model (by software)




d. Left window will be shown

e. Select "Hardware" tab

f. Check ODD model

→ It should be "TS-L632H"


■ Re-flashing Service Firmware



- Copy one click tool to background
- Double click the copied program for firmware re-flashing
(Firmware will be upgraded automatically)



■ Reflashing Service Firmware



c. After finishing the firmware re-flashing, above message will be shown



JUDGMENT STANDARD

■ CAUTION

- Disc should be removed before starting firmware re-flashing
- Close all program before starting firmware re-flashing
(Windows will restart automatically after re-flashing firmware)
- This program is only for TSST TS-L632H (TSST slim PATA)

Thank You !

